



Service & Repair History

[Check Records](#)



Accident & Title History

[Check Records](#)



Market Value Fair Price

[Check Records](#)



Odometer Records Check

[Check Records](#)



VIN: 1GBLP37J9W3311057

Year: 1998 Make: Chevrolet Model: P30

Details info. on VIN: 1GBLP37J9W3311057

Year: 1998

Make: Chevrolet

Body_type: MOTORHOME

Model: P30

Drive_type: RWD

Doors: 2

Engine_description: 7.4L V8 OHV 16V

Engine_capacity: 7.4 L

Fuel_type: Gasoline

Manufacturer: General Motors Company

Country: United States

Vin: 1GBLP37J9W3311057

Engine_size: 7.4

Engine_number_of_cylinders: 8

Displacement_(cc): 7440

Displacement_(ci): 454

Engine_model: V8

Region: North America

Note: Manufacturer Builds More Than 500 Vehicles Per Year

Source: USDecode

Selling your Vehicle?

The sticker on the window is a rich source of essential information about your automobile. The window sticker lets your buyer know exactly what’s included particularly in your car.

[View our Sample Window Sticker](#)

[Get your Windows Sticker](#)



Service Maintenance Records

For your Vehicle 1998 CHEVROLET P30
At the Mileage of 55000 mi
Against the VIN 1GBLP37J9W3311057

A QUICK SUMMARY OF YOUR VEHICLE
If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.

SAFETY RECALLS 2 items
Your vehicle has 2 Safety Recalls. These are announcements made by your vehicle's manufacturer that there is a safety-related problem that needs immediate repair and should be repaired free of charge by your vehicle's dealership. → View your recall notices here.

WARRANTY STATUS
Below is your default warranty information. This excludes any additional warranty coverage you may have purchased.
× Basic new car warranty 3 years × Powertrain warranty 3 years × Federal emissions warranty 8 years
If the vehicle is covered. If the vehicle is not completely covered. If the vehicle is not covered.

UPCOMING ISSUES 2 items
By analyzing other vehicles of the same year make model our results show you may need the following repairs in the next 12 months. It is recommended that you have these parts inspected by a trusted technician, and replace as needed.
36% Likelihood of Replace Mass Air Flow (MAF) Sensor \$443 Cost of repair \$341 in parts 27% Likelihood of Replace Oxygen Sensor(s) (O2S) \$223 Cost of repair \$121 in parts

\$102 in labor	\$102 in labor
Repair difficulty	Repair difficulty
	

This information can help you make strategic decisions about bidding and budgeting by showing you where you're succeeding and where you may be missing opportunities for improved performance.

Upgrade your Report

This Instant Vin Reports Report is based only on information acquirable by Instant Vin Reports as at the time of generating this report. Note that other information about this vehicle, including problems and services, may not have been reported to Instant Vin Reports. You are strongly advised to use this report only as an additional but important tool, along with the vehicle inspection and test drive, to make an informed decision about the purchase of this vehicle. © 2022 Instant Vin Reports. All Rights Reserved.